Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	380313	(determin\$5 or detect\$5 or measur\$5 or monitor\$5 or analyz\$5 or inspect\$5 or calculat\$5) near3 (stress\$2 or temperture or deform\$5 or pressure or dent)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:47
L2	9492	bragg near2 grating\$2	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2005/11/21 08:07
L3	328703	filter and (\$5detector or \$5sensor)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:07
L4	9222	(wideband or bradband or ((wide or broad) near2 band)) near4 (light or laser or source or beam)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:35
L5	39	1 and 2 and 3 and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:48
L6	65	plurality near3 ((\$5sensor or \$5detector) and (bragg near2 grating\$2))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:46
L7	3	6 and 1 and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:46
L8	406661	(determin\$5 or detect\$5 or measur\$5 or monitor\$5 or analyz\$5 or inspect\$5 or calculat\$5) near3 (stress\$2 or temperture or deform\$5 or pressure or dent or strain\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:33
L9	62	8 and 2 and 3 and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:48

				<u> </u>	T	
L10	23	9 not 5	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 08:48
L11	358678	optic\$2 near2 fiber	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:20
L12	315	11 and 8 and 3 and 4	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:22
L13	3980	(356/73.1,450,451,452,453,454, 455,456,457,458,459,460,35.5). CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 09:22
L14	656	(250/227.13,227.18,227.23).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 09:23
L15	5595	(385/12,14).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 09:23
L16	10052	13 or 14 or 15	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:23
L18	35	16 and 8 and 2 and 3 and 4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:24
L19	795557	(determin\$5 or detect\$5 or measur\$5 or monitor\$5 or analyz\$5 or inspect\$5 or calculat\$5) near3 (stress\$2 or temperature or deform\$5 or pressure or dent or strain\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:33

L20	86	19 and 2 and 3 and 4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:35
L21	84	20 and 11	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:35
L22	10	(((wideband or bradband or ((wide or broad) near2 band)) near4 (light or laser or source or beam)) and (bragg near2 grating\$2) and (filter and (\$5detector or \$5sensor))).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/11/21 09:36